General Information and Fire/Life Safety History

Inspection Date:

12/13/24

1. Primary Use:

INSTRUCTIONAL

2. Fire Sprinkler System?

Yes

2a. Sprinkler alarm?

Yes

3. Fire Hydrant System?

Yes

3a. Hydrant Ownership:

Public owned

4. Building Ownership:

Owned

5. Leased To Others?:

No

6. Square footage:

75413

8a. Fire drill manuals distributed?

Yes

8d. Average evacuation time:

2 minutes 25 seconds

8e. Arson/Fire Prevention?

Yes

8f. Prevention/Evacuation Training?

Yes

9. Fire Dept. notified via alarm?

Yes

10. Any Fires?

No

10a. Number of fires:

Not Applicable

10b. Number of injuries:

Not Applicable

10c. Cost of Damage:

Not Applicable

Inspector Notified of previous fire report?

Yes

FIRE & EMERGENCY DRILLS

	Date	Туре
1	Oct 12, 2023	Evacuation
2	Oct 12, 2023	Evacuation
3	Oct 17, 2023	Evacuation
4	Oct 19, 2023	Evacuation

68

	Date	Туре
5	Oct 19, 2023	Evacuation
6	Oct 24, 2023	Evacuation
7	Oct 25, 2023	Lockdown
8	Dec 7, 2023	Lockdown
9	Jun 4, 2024	Evacuation
10	Jun 12, 2024	Evacuation
11	Feb 7, 2024	Lockdown
12	Mar 19, 2024	Lockdown

Initial Inspector

PATRICK LEWIS

Phone #: (Phone Number) (716) 289-5672

Certification #: (Certification Number) 0610-7035B

Email: PATLEW55@AOL.COM

Building Administrator

MEL ALSTON

Phone #: (Phone Number) (716) 816-3564

Building Overview

ID:

140600010068

District Location:

BUFFALO CITY SD

Building Type:

INSTRUCTIONAL

Name & Address:

PUBLIC SCHOOL #68

24 WESTMINSTER

BUFFALO, NY 14215

Inspection History

Date Created:

Dec 15, 2024

Created By:

yvette.gordon

Date Modified:

Dec 24, 2024

Modified By:

tonja.williams2

Date Certified:

Dec 24, 2024

Certified By:

tonja.williams2

Certificate History

Certificate Type

Date Certified

Certified By

Certificate of Occupancy

Dec 24, 2024

tonja.williams2

Non-conformances

No non-conformances reported.

NYSED Home | Facilities Planning Home | Home | Terms of Use | Accessibility | Privacy Policy